



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Water Rights

MICHAEL R. STYLER
Executive Director

JERRY D. OLDS
State Engineer/Division Director

July 3, 2008

ROBYN BAILEY
SILVER SPRINGS MASTER
HOMEOWNERS ASSOCIATION
4915 SILVER SPRINGS RD
PARK CITY, UT 84098

DIVISION OF WATER RIGHTS - DAM SAFETY SECTION

DAM INSPECTION REPORT - 2008

Dam Name/Number:	Silver Springs No. 1 (Lower) UT00180		
Date:	7/1/2008	Dam Type/Hazard:	Moderate Hazard
Storage Level:	Full	Spillway & Res. Level Diff:	≈ 1" over west outlet
Spillway Flow:		Purpose of Inspection:	Biennial
Outlet Flow:	≈ 2 cfs	Weather: 85° sunny	

Representatives at the Inspection:

Name	Representing
Ross Hansen	Division of Water Rights
Les Carriel	Silver Springs Master HOA

Comments:

1. Remove trees and woody vegetation from the embankment.

Necessary Maintenance and Repair:

1. Maintain outlets clear of debris.
2. Remove trees and woody vegetation within 25' of embankment.

Embankment:

Crest:	Trees and woody vegetation.
US Slope:	Inundated, but some minor woody vegetation visible.
DS Slope:	Trees and woody vegetation.

Abutments/Foundation:	
L Abutment:	Trees and woody vegetation.
R Abutment:	Trees and woody vegetation.
US Toe:	Inundated.
DS Toe:	Trees and woody vegetation.
Reservoir Basin:	
Shore Stability:	OK
Reservoir Bottom:	Inundated.
Outlet:	
Conduit:	OK
Intake:	OK
DS Channel/Stilling Basin:	OK
Controls / Venting:	OK

Your cooperation is appreciated. If you have any questions, please feel free to contact Ross Hansen at (801) 538-7397.

Sincerely,



David K. Marble, P.E.
Assistant State Engineer

DKM/jm

pc: Ross Hansen - Water Rights Regional Engineer
Brian Davenport Mt Regional Water